Thursday, 06/11/2008 2:22:45 PM

User:

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Drawing Number

Project Number

Customer

Prsht Rev.

: CU-DAR001 Dart Helicopters Services

Type

Job Number **Estimate Number**

S.O. No. :

: 43243 : 13644

P.O. Number

This Issue

: 06/11/2008 : NC

First Issue : //

Previous Run

Written By

Checked & Approved By

Comment

: Est Rev:A New Issue 08-11-06

: SMALL /MED FAB

JLM

Verified By:EC

: A **Drawing Revision**

Material **Due Date**

: 07/11/2008

: SPACER

: D32345

: N/A

: D3234 REV A

Qty:

12 **Um**:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

5052-H32 .050 Sheet

1.0

M5052H32S050

Comment: Qty.: 0.0231 sf(s)/Unit

Total: 0.2772 sf(s)

5052-H32 .050 Sheet

BATCH:

2.0

WATER JET

FLOW WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D 3234

Dwg Rev:_ Prog Rev:_ 1B 8-11-7

2-Deburr if necessary

3.0 QC2



HB 8-11-7

Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK

Comment: SECOND CHECK

QC8

5.0

4.0

HAND FINISHING1

HAND FINISHING RESOURCE #1

Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1



Dart A

Page 1

Form: rproce

erospace l	_td
------------	-----

WORK ORDER CHANGES						
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				!		
	STEP					STEP PROCEDURE CHANGE By Date Qty Chief Eng /

Part No:		PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed	l:	Date:

NCR:	WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Verification	Approval	Approvai
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
								,


NOTE: Date & initial all entries

User: L	hursday, 06/11/2008 2:22:45 PM inda Lacelle	Process Sheet
Custom	er: CU-DAR001 Dart Helicopters Services	Drawing Name: SPACER
Job Numb	er: 43243	Part Number: D32345
Job Number:		
Seq. #:	Machine Or Operation:	Description :
6.0	QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION
	ment: INSPECT POWDER COAT/CHEMI	13/45/
7.0	PACKAGING 1	PACKAGING RESOURCE #1
Com	Iment: PACKAGING RESOURCE #1 Identify and Stock Location:	/ A1/11(a) Duy
8.0	QC21 (FINAL INSPECTION/W/O RELEASE
Com	ment: FINAL INSPECTION/W/O RELEAS	<u> </u>
Job Completion		MF 08-11-11





\	DESIG	P	DRAWN BY		AEROSPACE LTD (ESBURY, ONTARIO, CANADA	
	CHEC	(ED)	APPROVED,	DRAWING NO.		REV. A
		#		D3234	SHEET	1 OF 1
	DATE			TITLE		SCALE
	03.1	1.19		DOUBLER		1:3
	Α		03.11.19	NEW ISSUE		



D3234-1/-3 DOUBLER, D3234-5 SPACER

- 1) MACHINE PARTS PER DWG FILE "D3234-A.DWG"
- 2) MATERIAL: -1/-3: 2024-T3 (QQ-A-250/4), 0.050 THICK (REF DART SPEC. M2024T3S.050) -5: 5052-H32 (QQ-A-250/8), 0.050 THICK (REF DART SPEC. M5052H32S.050) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES

Copyright © 2003 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART APPOSDACE I	rn	Work Order	1 43243
DART AEROSPACE L	10		
Description:	SARER "	Part Number	: 03234-5
Description.	Sprovio		
Inspection Dwg: D3234-4	Rev: A		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X First Article X Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Rejest	Method of Inspection	Comments
2300	4/610	2,395	×			
1.340	-1 .010	· ·	X			
1050	+/- :010	,050	X a			
	-				**	· · · · · · · · · · · · · · · · · · ·
	, in 1985					
·	·				·.	
						ţ
				•		
·	•					
		·				
		·				
		`	·			
						-
						<u>.</u>
	.s	·			10 mg	
				3		
		. 4				

Measured by:	B .**	Audited by:	7	Prototype Approval:	W
Date:	8-11-7	Date: 0	8/4/10	Date:	19
<u> </u>	La-,,				

Rev	Dáte	Change	Revised by Approve	≱d
Α		New Issue	KJ/JLM	

